


FIGURE 2



LEGEND

- BULK OIL SAMPLE POINT
- MACHINE WIPE SAMPLE POINT
- BULK GREASE SAMPLE POINT
- MACHINE W/I.D. NUMBER

Samples
3-19-98

BOSSERT SITE
(SITE CODE: 6-33-029)


MACHINE
SAMPLING
POINTS

NOT TO SCALE

0450.046.OIF


Stetson-Harza
A HARZA COMPANY
181 Conness Street, Troy, NY 12180 (518) 797-5800
Rensselaer Technology Park
250 Jordan Rd., Troy, NY 12180 (518) 283-8080

439037



NOTES:

1. SAMPLES WERE COLLECTED FROM DECEMBER 6 THROUGH DECEMBER 16, 1993.
2. THE FIELD SAMPLING CREW WAS COMPRISED OF PATRICIA ROSATO, KYLE THOMAS AND JEFF BULLIS.
3. THE FOLLOWING ANALYSES WERE PERFORMED:
 - WIPE SAMPLING FOR PCB'S ON PRESSES, METAL DEBRIS, DRUMS AND CRATES
 - BULK SAMPLING PCB'S ON DEBRIS AND FLOOR SWEEPINGS, OIL RESERVOIRS, SUSPECTED ASBESTOS CONTAINING MATERIAL AND CRATES.
 - BULK SAMPLING TCLP ON DEBRIS AND FLOOR SWEEPINGS, GREASE LINES, OIL RESERVOIRS AND DRUM CONTENTS.
4. H2M LABORATORY OF MELVILLE, NY PERFORMED ANALYSIS OF ALL SAMPLES.
5. DATA VALIDATION BY DATA VALIDATION SERVICES, NORTH CREEK, NY.



FIRST FLOOR PLAN